

VEHICLE INSPECTION REPORT

217789

HONDA HRX537 C5HYE

Inspection

Vehicle

VAT	Plus VAT
V5	Not Present

Details

Reg. date	Mileage	TBC	Colour
Year	Fuel Type		VIN
2020			MAMA1217789

MOWER, HONDA GCVX 200 PETROL ENGINE *PULLS DOES NOT START*

Tyres

NSF
NSR
OSF
OSR
Spare

Photos

